

INSTALLATION INFORMATION SHEET

ZA4012

Mounting hardware-kit for mounting one worklight of CR-1030 or CR-1031. The bracket is mounted to the back of the worklight. The hood mounting method varies in placement.



CONTENT OF THE BOX:



1x adapterplate
ZA4012



3x self locking
nut M4



3x screw
M4 x 15mm




3x washer



1x screw
M4 x 24mm

PARTS NEEDED FROM LIGHT PACKAGE FOR INSTALLATION:



grey seal ring




adaptercable 9005 female – H9 male

HOLE EXPLANATION:


Lower worklight:

Upper worklight:



New Holland T5 / T6 / T7 - Upper worklight

Screws needed from light package:



2x screw
M4 x 24mm



3x screw
M4 x 15mm




3x self locking
nut M4



1x screw
M4 x 24mm




3x washer



New Holland T5 / T6 / T7 - Lower worklight

Screws needed from light package:



3x screw
M4 x 24mm



3x screw
M4 x 15mm



3x self locking
nut M4



1x screw
M4 x 24mm



3x washer

